

Funktioniert mit Kernelpatch nur bis kernel 3.12.38-gentoo. Patch liegt am Backup oder lokal auf der VM. Ein Kernelpatch kann folgender Maen eingespielt werden:

```
patch -p1 < /root/dvbdriver/kernel-3.12.5-dvbsky.patch
```

Anhngte Kernelconfig ist von Kernel 3.12.38. Hier ist zwingend Genkernel erforderlich, da die Maschine sonst ewig zum Booten bentigt. Wichtig ist hier das es verdammt viele Abhngigkeiten gibt damit die erforderlichen Treiber fr die Karte berhaupt aufscheinen. Das ganze sieht dann so aus:

### --- Multimedia support

```
*** Multimedia core support ***
[*] Cameras/video grabbers support
[ ] Analog TV support
[*] Digital TV support
[ ] AM/FM radio receivers/transmitters support
[*] Remote Controller support
[*] Media Controller API
[*] V4L2 sub-device userspace API
[ ] Enable advanced debug functionality on V4L2 drivers
[ ] Enable old-style fixed minor ranges on drivers/video devices
< > V4L2 int device (DEPRECATED)
[*] DVB Network Support
(8) maximum number of DVB/ATSC adapters
[ ] Dynamic DVB minor allocation
*** Media drivers ***
< > Compile Remote Controller keymap modules
[ ] Remote controller decoders ----
[ ] Remote Controller devices ----
[*] Media PCI Adapters --->
[ ] V4L platform devices ----
[ ] Memory-to-memory multimedia devices ----
[ ] Media test drivers ----
*** Supported MMC/SDIO adapters ***
*** Supported FireWire (IEEE 1394) Adapters ***
< > FireDTV and FloppyDTV
*** Media ancillary drivers (tuners, sensors, i2c, frontends) ***
[*] Autoselect ancillary drivers (tuners, sensors, i2c, frontends)
Sensors used on soc_camera driver ----
```

## --- Media PCI Adapters

```
*** Media capture support ***
*** Media capture/analog/hybrid TV support ***
<M>   Conexant cx23418 MPEG encoder support
<M>   Conexant 23418 DMA audio support
<M>   Conexant cx23885 (2388x successor) support
<M>   Altera FPGA based CI module
<M>   Conexant cx25821 support
<M>   Conexant 25821 DMA audio support
<M>   Conexant 2388x (bt878 successor) support
<M>   Conexant 2388x DMA audio support
<M>   Blackbird MPEG encoder support (cx2388x + cx23416)
<M>   DVB/ATSC Support for cx2388x based TV cards
[ ]   VP-3054 Secondary I2C Bus Support
< >  BT848 Video For Linux
< >  Philips SAA7134 support
< >  NXP SAA7164 support
```

Jetzt muss noch die richtige Firmware eingespielt werden: Aus dem Firmwarepack benötigt man lediglich die Dateien „**dvb-fe-ds300x.fw**“ und „**dvb-fe-ds3103.fw**“. Diese verschiebt man nach **/lib/firmware/**.

Nach erfolgreichen Booten des Systems müssen folgende Module geladen sein:

```
lsmod | grep cx23885
cx23885                134497  7
btcx_risc              2731    1 cx23885
altera_ci              7294    1 cx23885
videobuf_dvb          4106    1 cx23885
tda18271              32378   1 cx23885
videobuf_dma_sg       6642    1 cx23885
tveeprom              12625   1 cx23885
videobuf_core         12529   3 videobuf_dma_sg,cx23885,videobuf_dvb
cx2341x                13877   1 cx23885
snd_pcm                60884   1 cx23885
snd                    43924   3 cx23885,snd_timer,snd_pcm
```

Folgende Geräte müssen existieren:

```
/dev/dvb/adapter0/
/dev/dvb/adapter1/
```

Ab jetzt funktioniert die Karte.

From:  
<https://deepdoc.at/dokuwiki/> - **DEEPDOC.AT - enjoy your brain**

Permanent link:  
[https://deepdoc.at/dokuwiki/doku.php?id=installation\\_dvbsky\\_unter\\_gentoo&rev=1426622052](https://deepdoc.at/dokuwiki/doku.php?id=installation_dvbsky_unter_gentoo&rev=1426622052)

Last update: **2025/11/29 22:06**

